

From February 9, 2017, Modified 48-month Inspection Interval Criteria

On January 23, 2017, FHWA approved a modification to the 48-month inspection interval criteria outlined in Section 3.4.1.1 of the *Structural Services Manual*.

The current criteria that all Deck, Superstructure, and Substructure or Culvert (ISIS Items 58, 59, 60 and 62 respectively) condition ratings must be "7" (good condition) or greater has been modified.

Structures with a Deck (ISIS Item 58) condition of "6" and meeting all other 48-month inspection interval criteria shown in Section 3.4.1.1 will be allowed to have a 48-month inspection interval.

The modified inspection interval was calculated for structures in ISIS February 8, 2017. The modified 48-month inspection interval policy will be included in the next edition of the *Structural Services Manual*.