



Illinois Department of Transportation

2300 South Dirksen Parkway / Springfield, Illinois / 62764

BDE PROCEDURE MEMORANDUM

NUMBER: 12-08

SUBJECT: BDE Manual Revision – Chapter 36

DATE: August 3, 2012

Chapter 36 of the BDE Manual has been revised to change the width of the gutter pan along the outside edges of the curbed median for Figure 36-3.O. Please see Chapter 36 of the BDE Manual on-line to view the revisions.

Background

Previously Figure 36-3.O showed a 6 inch gutter pan along the outside edges of the curbed median. Therefore, if a storm sewer inlet was required, a special detail would be necessary to locate it, since a 6 inch gutter pan is not wide enough to accommodate a standard storm sewer inlet. To accommodate standard storm sewer inlets, a 24 inch gutter pan is now shown with all curb in the figure.

Engineer of Design and Environment _____

A handwritten signature in black ink, appearing to be 'C. R.', written over a horizontal line.